

Product info sheet


Robert Bosch

0445110634

Special tools needed?

Yes

Injectors can be very stuck. Please contact us if you don't have the right equipment.



Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No


Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2



Tightening torques

Injector/ retaining clamp

35 Nm

High Pressure pipe nuts

32 Nm

Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Recommendation: replace sealing ring

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

