



LuK Service Info

Part Nr. 228 0181 10 – 280/280MM KGS6

Manufacturer: CASE IH, NEW HOLLAND

CASE IH – JX60, JX 70

NEW HOLLAND – TD5010, TD5020, TD60D, TD70D



TB1438

Art.-Nr.: 228 0181 10

**Info: 628 3565 09 replaces / ersetzt
/ remplace / sustituye a / sostituisce
228 0181 10**



628 3565 09 = 228 0181 10 + 328 0332 10



**228 0181 10
OE 509 7959**



628 3565 09

**Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com**

**SCHAEFFLER
REXPERT**