



INA Service Info



Over-running alternator pulley 535 0330 10

Visual differences

Manufacturer: Hyundai, Kia

Models:

Hyundai: ix 55

Kia: Borrego, Mohave

Engine: 3.0 diesel

Alternator:

Denso: 104210-1741

Part no.: 535 0330 10

For current listing refer to catalogue media



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 535 0330 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk

SCHAEFFLER
REP>XPERT