



# CLUTCHTECH



## TSB-FD091

### Ford Transit Thrust Bearing Failure

Applies to ClutchPro kit:

KFD25008 (KFD25508)

KFD25009 (KFD25509)

KFD25021 (KFD25521)

When fitting a clutch kit to Ford Transit 2.4l TD it is important to check the condition of the thrust bearing guide tube. The guide tube is a screw in type which can come loose. When this happens the guide tube cocks allowing the thrust bearing to hold on causing the thrust bearing to fail.

The guide tube is available from ClutchPro, part number ATFFD-NC

Also available:

- ATFFD-NCS Shaft Seal
- ATFFD17 Clutch Fork (04/02-03/04)
- ATFFD18 Clutch Fork (03/00-04/02 and SMF conversion)



#### LEADING BRANDS

CLUTCHPRO CLUTCHPRO



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)