



CLUTCHTECH





TSB-PR001

Applicable to all TB34008 Thrust Bearings

Thrust Bearing Component Assembly Order

Please ensure the order of components is correct when assembling the bearing in the diaphragm. Failure to install the components in the correct order can result in the clutch not operating correctly and causing excessive wear/ noise.



LEADING BRANDS

CLUTCHPRO CLUTCHPRO



australianclutch.com.au

1800 CLUTCH (258824)