TECHNICAL

BUIDER





Bulletin Ref: TB1a

AAL1438

This vehicle could have an option of several different units fitted.

Please double check the pulley and connection points before ordering and attempting to fit to the vehicle.





