

## **Mercedes Sprinter**

This vehicle could have an option of several different units fitted.

This unit replaces the following original part numbers 0124325169, 0124325170.

Please double check before ordering and fitting to the vehicle



AAL1552





For further information on this or any other issue contact the Apec technical team by phone or email at: Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US #TechMate | @TechMateAuto