

## APEC THERMOSTAT ATH1592

Ford have modified the design of the thermostat installed on the Ford Transit 2.0 TDCi 05/2016 – 07/2019. The early version OE part number 2037317 with a 3 bolt fixing and two sensors has been replaced by OE part number 2347347 which has only 2 bolt fixings and a single sensor.



**OE part number 2347347**

Please note: As the new thermostat only has a single sensor for all applications between 05/2016 - 07/2019, there will be a spare loom connector, which is no longer required.