

## Product info sheet

Robert Bosch

0445110418

Special tools needed?

No

## Product specific information

Programming

Yes

IMA code (8 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

ignition on for 30 seconds

adjustment at mounting\_1

No

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

26 Nm

High Pressure pipe nuts

25 Nm

## Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Replace tension bolts

Recommendation: replace gasket fuel connection

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

