

Product info sh	leet	Robert Bosch	0445115028
Special tools needed?	No		
		oduct specific inform	ation
Programming	Yes	IMA code (7 characters)	L
			IMA
Unlocking	No No		
Adaption values reset Bleed	No		
adjustment at mounting_1			
		1	
adjustment at mounting_2			
Tightening torques			
Injector/ retainingclamp		22 Nm	
High Pressure pipe nuts		23 Nm	
Assembly instructions			
Replace sealing washer		,	
Replace tension bolts			
Core charge terms:			
-externally intact,			
-no mechanical damage,-not dismantled,			
-no heavy corrosion.			