

## Product info sheet

Robert Bosch

0445117026

Special tools needed?

Yes

Use special tool to turn the coupling nut.



## Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

Activate feed pump by OBD

adjustment at mounting\_1

No

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

8 Nm + 90°

High Pressure pipe nuts

25 Nm

## Assembly instructions

Replace sealing washer

Replace tension bolts

Replace injector clamp

Recommendation: replace fuel filter

Recommendation: replace gasket fuel connection

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

