



Product info sheet

Robert Bosch

0445120065

Special tools needed?

No

Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

Tightening torques

Injector/ retaining clamp

10 Nm + 90°

Bushing inlet pipe

80 Nm

Straining screw inlet pipe

1: 15 Nm -> tighten injector -> 2: 42 Nm

Electrical connectors injector

1,5 Nm

Assembly instructions

Recommendation: replace fuel filter

Recommendation: replace sealing ring

Replace sealing washer

Replace inlet pipe

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.