

## Product info sheet

VDO

A2C3335190080

Special tools needed?

No

## Product specific information

Programming

Yes

Calibration code (9 characters)

Unlocking

No

Adaption values reset

No

Bleed

No

adjustment at mounting\_1

No

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

5 Nm + 185°

## Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Replace injector clamp

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.