

Product info sh	eet	Denso	DCRI107670
Special tools needed?	No		
	Pi	roduct specific info	rmation
Programming	Yes	ID code (30 characters)	(0) \$514 0E12
			1415 ZATB 3400 0A
Unlocking	No		
Adaption values reset	Yes	Reset adaptive values	
Bleed	Yes	Use manual pump on ve	ehicle
adjustment at mounting_1			
adjustment at mounting_2			
		Tightening torq	IIES
Injector/ retainingclamp		25 Nm	des
Banjo fuel fitting		20 Nm	/
High Pressure pipe nuts		34 Nm	
Bolts valve cover		11 Nm	
boits valve cover		111111	
		Assembly instruc	etions
Docommondation:	coaling ris	•	
Recommendation: replace Replace sealing washer	sealing ring		
Replace Sealing Washer			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled,			
-no heavy corrosion.			