

## Product info sheet

Robert Bosch

0445116034

Special tools needed?

Yes

Use special tool to turn the coupling nut.



## Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

Activate feed pump by OBD

adjustment at mounting\_1

No




adjustment at mounting\_2

No




## Tightening torques

Injector/ retaining clamp

8 Nm + 180°

High Pressure pipe nuts

28 Nm






## Assembly instructions

Replace tension bolts

Recommendation: replace fuel filter

Replace sealing washer

Recommendation: replace sealing ring

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

