




EGR VALVES WITH COOLER

FITTING NOTE FOR PTA510-0265



Please replace necessarily the enclosed heat insulator (OE No. 03L 131 531 A) and fit as displayed to the vacuum actuator. The fastener button must be locked tightly!

ATTENTION:


The notch must be kept loose for the connection of the vacuum hose [step 3]!



ASSEMBLY:



STEP 1



STEP 2



STEP 3



STEP 4

