Service Information | Serviceinformationen



Replacement of MDB3754 by MDB2063.

Mintex is now able to harmonize the references MDB3754 by MDB2063. It was proven that MDB2063 can also cover the applications of MDB3754. Therefore Mintex will replace MDB3754 by MDB2063.

The main difference between them is the friction material shape. Therefore there will be no difficulties during installation and operation.



As usual, existing stock of MDB3754 can be sold out without any problems.