Service Information | Serviceinformationen



Replacement of MDB1647 with MDB3103

Mintex will harmonise the reference MDB1647 with MDB3103.

The only difference between the references was the friction material, therefore there will be no difficulties during assembly and operation.

MDB1647 was used globally and MDB3103 was only for Germany (we now consider the use of the MDB3103 version globally).

By doing this harmonisation, more vehicles are covered with just one reference (MDB3103).

MDB1647





MDB3103

As usual, the existing stock of MDB1647 can be sold without any problems.