

HJS Montage Information | HJS Mounting Information

Nur für Range Rover EVOQUE (L538 MJ 2016)/

Discovery Sport 2.0D (L550 AJ20D MJ 2017):

NOx-Sensor LR093669 (Sensor hinter SCR-Katalysator erneuern)

Beim Austausch des OE NOx-Sensors LR093669 (GH22-5J299-AD) wird das beiliegende Adapterkabel/Steckverbindergehäuse (LR153923) benötigt.

Only for Range Rover EVOQUE (L538 MJ 2016)/

Discovery Sport 2.0D (L550 AJ20D MJ 2017):

NOx sensor LR093669 (replace sensor behind SCR catalytic converter)

When replacing the OE NOx sensor LR093669 (GH22-5J299-AD), the enclosed adapter cable/connector housing (LR153923) is required.