



**ALTERNATEUR ROVER**

 Remanufactured

FADAAL

Core code : 08

 3599771218259




## TECHNICAL DATA

Alternator Charging Current [A]	<b>85 A</b>
Fiche	<b>PLUG599</b>
Pulleys	<b>with V-ribbed belt pulley</b>
Info complémentaire	<b>with integrated regulator</b>
Connector/Clamp	<b>with connection for speed sensor</b>
Number of grooves	<b>6</b>
Clamp	<b>M6 B+</b>
Voltage [V]	<b>12 V</b>

## PICTURES



 Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

<b>ROVER</b>		
200 Hatchback (XW) - 220 GTi	136 ch	01.1993 > 10.1995
	140 ch	09.1991 > 10.1995
200 Hatchback (XW) - 220 Turbo	200 ch	<b>01.1993 &gt; 10.1995</b>
200 Coupe (XW) - 220 GSi	136 ch	05.1994 > 06.1999
200 Coupe (XW) - 220 Turbo	200 ch	10.1992 > 06.1999
400 (XW) - 420 GSi/SLI/GTI/Vite	136 ch	01.1993 > 04.1995
400 (XW) - 420 GTI/GSi/Vitesse	140 ch	02.1992 > 04.1995
400 (XW) - 420 Turbo	200 ch	01.1993 > 04.1995
400 Hatchback (RT) - 420 Si Lux	136 ch	12.1995 > 03.2000
400 (RT) - 420 Si Lux	136 ch	12.1995 > 03.2000
600 (RH) - 620 Ti Vitesse	200 ch	05.1994 > 08.1998
800 Hatchback (XS) - 820 Si	133 ch	10.1988 > 12.1991
800 Hatchback (XS) - 820 i/Si	140 ch	10.1988 > 12.1991
800 Hatchback (XS) - 820 I/SI	136 ch	01.1991 > 02.1999
800 Hatchback (XS) - 820 16V Turbo	180 ch	11.1991 > 02.1999
800 (XS) - 820 Si	133 ch	10.1988 > 12.1991
800 (XS) - 820 I/SI	136 ch	01.1992 > 02.1999
800 (XS) - 820 16V Turbo	180 ch	01.1992 > 02.1999
800 Coupe - 820 16V	136 ch	07.1997 > 02.1999