



ALTERNATEUR LAND ROVER DI

 Remanufactured

FADAAL

Core code : 08


 3599771210130



TECHNICAL DATA

Alternator Charging Current [A]	130 A
Fiche	PLUG381
Pulleys	with V-ribbed belt pulley
Info complémentaire	with integrated regulator
Number of grooves	7
Clamp	M8 B+
Voltage [V]	12 V

PICTURES



 Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.



LAND ROVER

DISCOVERY (98-04) (LJ, LT) - 4.0 V8 4x4	185 ch	11.1998 > 06.2004
---	--------	-------------------