



ALTERNATEUR BRAVA, BRAVO

 Remanufactured

FADAAL

Core code : 07

 3599771203569




TECHNICAL DATA

Alternator Charging Current [A]	85 A
Fiche	PLUG381
Pulleys	with V-ribbed belt pulley
Info complémentaire	with integrated regulator
Technical Information Number	BT-35
Number of grooves	6
Clamp	M8 B+
Voltage [V]	12 V

PICTURES



 Before installation, compare the part received with the original part to ensure that the correct part number has been selected and can be installed on the vehicle. Failure to follow those, or the manufacturer, instructions will void the warranty.

FIAT		
BRAVO (95-01) (182) - 2.0 HGT 20V	147 ch	10.1995 > 07.1998
	154 ch	07.1998 > 10.2001
COUPE (FA/175) - 2.0 20V	147 ch	08.1996 > 09.1998
	154 ch	04.1998 > 08.2000
COUPE (FA/175) - 2.0 20V Turbo	220 ch	08.1996 > 08.2000
MAREA (185) - 2.0 150 20V	147 ch	09.1996 > 04.1999
	150 ch	01.2001 > 05.2002
MAREA (185) - 2.0 155 20V	154 ch	04.1999 > 01.2001
MAREA Weekend (185) - 2.0 150 20V	147 ch	09.1996 > 04.1999
	150 ch	01.2001 > 05.2002
MAREA Weekend (185) - 2.0 155 20V	154 ch	04.1999 > 01.2001

LANCIA		
LYBRA (839AX) - 2.0 20V	150 ch	09.2000 > 10.2005
	154 ch	07.1999 > 09.2000
LYBRA SW (839BX) - 2.0 20V	150 ch	09.2000 > 10.2005
	154 ch	07.1999 > 09.2000