


PI 1770

For technical personnel only!

1/1

PRODUCT INFORMATION

OUTSIDE OVERSIZE ENGINE BEARING

REPAIR SOLUTION FOR MERCEDES-BENZ OM 651

The main bearing seats of the OM 651 engine series cannot be reconditioned in a conventional way due to the cracked bearing caps. Motorservice offers a special set of outside oversize engine bearings to enable these engine blocks to be reconditioned.

This engine bearing set with larger outside diameter allows the engine reconditioner to condition the faulty main bearing seats of the engine block.



1	2	3	4	5	6	7	8	9	10
									
1	83	Cyl. 4	40 776 6., 40 809 6., 41 641 6.						
OM 651	901		D (LA)	4	1796 cm ³	4V	80-100 kW (109-136 PS)	16,2	83,00 mm
OM 651	911 - 912, 916, 921, 924 - 925, 940, 950, 955, 960 - 961, 980		D (A)	4	2143 cm ³	4V	70-150 kW (95-204 PS)		99,00 mm
OM 651	913, 930, 956 - 957		D (LA)	4	2143 cm ³	4V	70-130 kW (95-177 PS)	16,2	99,00 mm
HL	St/A	59,965	64,514	20,50	2,262	STD		4	77 973 700 (1)
HL	St/B/S F	59,965	64,514	20,50	2,262	STD			77 973 710 (1)
HL	SPUTTER	59,940	64,500			0,50			77 973 720 (1)
PASS-L	St/A	59,965	64,514	26,33	2,262	STD		1	
PASS-L	St/B/S F	59,965	64,514	26,33	2,262	STD			
PASS-L	SPUTTER	59,940	64,500			0,50			
	STD	26,500 - 26,540							
	0,25	26,500 - 26,540							
	0,50	26,500 - 26,540							
	Spiel / Clearance / Jeu / Juego - Axial / Зазор Осевой: 0,200 - 0,373								
(1)	Außenübermaß / outside oversize / surcote extérieure de / sobremedida exterior / припуском наружного размера + 0,50 mm								

Catalogue extract:
Outside oversize engine bearing set for Mercedes-Benz OM 651

All content including pictures and diagrams is subject to change. For assignment and replacement, refer to the current catalogues or systems based on TecAlliance.

OUR **HEART** BEATS FOR YOUR ENGINE.