




# CLUTCHTECH



## TSB-FN7-10-B86

When installing this clutch, it is important that the discs are orientated the correct way. Failure to do so will result in clutch actuation issues and potential damage.

The leaf sprung side (pictured) of each disc **MUST** face away from each other. Eg. Leaf side facing flywheel and the other disc leaf side faces the transmission.



### LEADING BRANDS

CLUTCHPRO CLUTCHPRO COMMERCIAL



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)