



CLUTCHTECH



TSB - MB02

Correct Slave Cylinder Identification for Mercedes Atego

If the vehicle has a semi automatic gearbox the CSC required is CSCMB016. On this cylinder it has a sensor for the gearbox to recognize clutch operation. (See picture below) These vehicles do not have a clutch pedal.



If the vehicle is fitted with a conventional gearbox the CSC required is CSCMB015. This cylinder has no sensor to recognize clutch operation. (See picture below)



LEADING BRANDS

CLUTCHPRO CLUTCHPRO



australianclutch.com.au

1800 CLUTCH (258824)