

**CLUTCHTECH**

## TSB-356

### Concentric Pneumatic Clutch Actuators

This kit contains a concentric pneumatic clutch actuator (CPCA) that must be calibrated using a suitable diagnostic device prior to operation. Failure to do this may result in operational issues and error messages on the vehicle information display.

If difficulty is experienced in calibrating the CPCA, possible causes are:

- Insufficient supply of compressed air
- Low air pressure due to clogged air filters



#### LEADING BRANDS

**CLUTCHPRO** **CLUTCHPRO**  
COMMERCIAL

For further support, please contact your distributor and/or visit our website.

AU site: [australianclutch.com.au](http://australianclutch.com.au)  
US site: [xclutchusa.com](http://xclutchusa.com)