## COMMON FAULTS



## NOW AVAILABLE FITTING KIT LVSK3001SK

FOR LAND ROVER DISCOVERY III. IV. RANGE ROVER SPORT



Motaquip's fitting kit LVSK3001SK allows for easier replacement of lower Land Rover suspension arms.

**Introducing LVSK3001SK lower** suspension arm fitting kit for **Discovery III, IV and Range Rover** Sport 2005-12.


A common fault on these vehicles is the lower wishbone bush bolts often become corroded making them difficult to remove. This makes lower wishbones (LVSA1224

& LVSA1225, or LVSA1397 &**LVSA1398**) difficult to replace. The bolts are usually destroyed when removed.

Motaquip have created **LVSK3001SK** to solve this problem as our kit has all the necessary ancillary parts to provide a new fitting kit with the new Wishbones.









## LVSK3001SK Kit Contains:

2 x RDI000034 2 x RYF000203 2 x WA116106

4 x FX116056 1 x RYG000440

Washer

Camber Washer

Camber Bolt

Strut Mounting Bolt 1 x RFD500020 Drive Shaft Nut

Part Number	Description	Make	Model	Year	Fitting Position
LVSK3001SK	Lower Wishbone Fitting Kit	Land Rover	Discovery III, IV Range Rover Sport	2004->	Front Axle Lower LH and RH
LVSA1224	Lower Wishbone LH	Land Rover	Discovery III, IV	2004->	Front Axle Lower LH
LVSA1225	Lower Wishbone RH	Land Rover	Discovery III, IV	2004->	Front Axle Lower RH
LVSA1397	Lower Wishbone LH	Land Rover	Range Rover Sport	2005->13	Front Axle Lower LH
LVSA1398	Lower Wishbone RH	Land Rover	Range Rover Sport	2005->13	Front Axle Lower RH