

Product info sheet

Robert Bosch

0445110265

Special tools needed?

No

Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed


No

adjustment at mounting_1

No

adjustment at mounting_2

--



Tightening torques

Injector/ retaining clamp

1: Nuts both sides: 6 Nm 2: Flywheelside: +360°

High Pressure pipe nuts

27 Nm

Assembly instructions

Replace bolts/studs and nuts

Replace sealing washer

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

