

| Product info sh | eet | VDO | | 13538616079 |
|---|--------------|---------------------|-----------|---|
| Special tools needed? | No | | | |
| | | | | |
| | | | | |
| Product specific information | | | | |
| Programming | Yes | Calibration code (6 | | |
| | | | | |
| Unlocking | No | | | 353 7585261-12 g >PA 6.6 GF35%< 580 % 101810 10 Italy |
| Adaption values reset | Yes | Reset adaptive val | ues | 243 |
| Bleed | No | | | |
| adjustment at mounting_1 | No | | | |
| | | | | |
| | | | | |
| a divetus out at manuating 2 | | 1 | | |
| adjustment at mounting_2 | |] | | |
| | | | | |
| | | | | |
| Tightening torques | | | | |
| Injector/ retaining clamp 15 Nm | | | | |
| , | | | | / |
| | | | | A |
| | | | | |
| | | | | |
| | | | | |
| | | Assembly inst | tructions | |
| Recommendation: replace | sealing ring | | | |
| | | | | |
| | | | | |
| Core charge terms: | | | | |
| -externally intact, | | | | |
| -no mechanical damage, | | | | |
| -not dismantled, | | | | |
| -no heavy corrosion. | | | | |