




# IMPORTANT PRODUCT DESIGN INFORMATION

This unit incorporates a floating back plate, which is secured when the unit is fitted to the gearbox mounting face. If the red transit clip is removed prior to fitment, the floating back plate will move and the concentric slave cylinder will leak.

1. Replace the O-ring seal with the new seal provided in the box.



2. Ensure the unit sits correctly on the gearbox mounting face. Tighten the bolts evenly to 11Nm.



3. Once correctly fitted to the gearbox, remove the red transit clip.



Red transit clip



## Need more support?

For comprehensive advice from one of our clutch experts, email [TGLSales@tibbettsgroup.com](mailto:TGLSales@tibbettsgroup.com)