


MDB1175 (WVA 20753) / MDB1883 (WVA 23103)

Mintex is harmonising the two references MDB1175 and MDB1883. MDB1883 will cover applications of both part numbers in the future. Therefore MDB1175 will be phased out.

The parts differ in the way the piston clip is mounted on the back plate. Furthermore, the overall length of MDB1883 is a bit smaller so that the pads can be fitted to those vehicles which previously used MDB1175, without any problems.




Existing stock of MDB1175 can be sold without any problems.

MDB1175 (WVA 20753) / MDB1883 (WVA 23103)

Mintex harmonisiert die beiden Artikel MDB1175 und MDB1883. Zukünftig wird MDB1883 alle Anwendungen beider Teilenummern abdecken. Infolgedessen wird MDB1175 auslaufen.

Die beiden Artikel unterscheiden sich in der Kolbenhaltefeder und der Art wie diese an der Rückenplatte angebracht ist. Zudem ist die Länge über alles bei MDB1883 ein bisschen geringer was es MDB1883 erlaubt, ohne Probleme in Fahrzeugen verbaut zu werden, die bisher MDB1175 nutzten.



Noch existierender Bestand von MDB1175 kann ohne Probleme verkauft werden.