## Service Information | Service-Information



## Replacement of 2489801 by 2489803

Textar is able to harmonize the references 2489801 and 2489803. It was proven that 2489803 can also cover the applications of 2489801. Therefore Textar will replace 2489801 with 2489803.

Textar decided to reduce the thickness of 2489803 to 14,0 mm, which makes the two references equal and therefore Textar decided to harmonise 2489801 with 2489803. There will be no difficulties during installation and operation.



As usual, existing stock of 2489801 can be sold out without any problems.