




EGR VALVES WITH COOLER

FITTING NOTE FOR PTA510-0264

Please replace necessarily the enclosed heat insulator (OE No. 03L 131531A) and fit as displayed to the vacuum actuator. The fastener button must be locked tightly!

ATTENTION:

The notch must be kept loose for the connection of the vacuum hose (step 3)!



ASSEMBLY:



