

NAL1732

Bulletin Ref: TB13n

This vehicle could have an option of 2 possible amperage units fitted. Please double check that the amperage on the unit removed corresponds to the one being ordered and fitted



Technical Support

Contact our expert technical team on 03333 136597 or email NAPAtechnical@allianceautomotive.co.uk



TECH TechMate Support

Book a TechMate visit today! Contact the team on 01174 288090 or email info@techmateteam.co.uk