TECHNICAL

BUIGHER





Bulletin Ref: TB15a

Check kW Rating

ASM1466

This vehicle could have an option of 3 different rated units fitted.

Please double check the kW rating of the unit being removed before fitting.







