TECHNICAL

BURGERIA





Bulletin Ref: TB15a

Check kW Rating

ASM1498

This vehicle could have an option of 3 different rated units fitted.

Please double check the kW rating of the unit being removed before fitting.







