



KNOW HOW

TECHNICAL BULLETIN





NAL1438

Bulletin Ref: TB1n

This vehicle could have an option of several different units fitted.

Please double check the pulley and connection points before ordering and attempting to fit to the vehicle.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk