



KNOW HOW



TECHNICAL BULLETIN



NAL1701

Bulletin Ref: TB3n

This vehicle has multiple options fitted. Please double check the OEM part number on the unit removed, this unit only corresponds to the following TG15C146.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk