



KNOW HOW



TECHNICAL BULLETIN



NSM1466

Bulletin Ref: TB15n

This vehicle could have an option of 3 different rated units fitted.
Please double check the KW rating of the unit being removed before fitting.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk